


- Electromechanic relations: counter electromotive force
- The armature has "N" active conductors and "a" winding paths
- The armature's counter-electromotive force is written:

$$E = \frac{N}{2a} \cdot e$$
  $E = \frac{N}{2a} \cdot 2p \cdot n \cdot \phi$   $E = \frac{p}{a} \cdot N \cdot n \cdot \phi$ 



- Usually written:  $E = k \cdot n \cdot \phi$ 


with k=(p/a)N a constant related to the construction of the machine

- Or also:  $m{E} = m{k_n}.\,m{n}$  if  $\Phi$  remains constant, permanent magnet motor or  $i_{\scriptscriptstyle E}$  =Cste

k<sub>n</sub>: speed constant, given by the manufacturer, in V.tr<sup>-1</sup>.s or V.tr<sup>-1</sup>.min




- Equivalent circuit of the DC motor:








- Equivalent circuit of the DC motor:
- Armature: Each active conductor is made of copper, has a length and a cross-section, and therefore has a resistance to current flow
- => The total armature resistance is called R<sub>A</sub>
- The equivalent models of both armature and inductor windings actually consist of a resistor R and an inductance L with no steady-state effect
- $\Rightarrow$  I<sub>A</sub> = Cste and L.dI<sub>A</sub>/dt = 0
- ⇒ L usually discarded for this reason







Inductor

- U<sub>A</sub>: supply voltage in Volts
- E:.c.e.m.f in Volts
- R<sub>A</sub>: armature resistance in Ohms
- I<sub>A</sub>: armature current in Amperes





- Characteristic equations:

- Expression of rotation speed:

$$n = \frac{E}{k. \Phi} = \frac{U_A - R. I_A}{k. \Phi} \cong \frac{U}{k. \Phi}$$

=> If the flux disappears, the motor goes into overdrive

$$n\cong \frac{U}{k_n}$$

=> The speed is proportional to voltage if the flux is constant

- Power absorbed by the armature:

$$P_A = U_A$$
.  $I_A$ 

- Power absorbed by the inductor:

$$P_E = U_E.\,I_E$$

- Total electrical power supplied to the motor:

$$P_{AbsTot} = U_A. I_A + U_E. I_E$$




- Characteristic equations:
- Inductor Joule losses:

$$\mathbf{P_{JE}} = \mathbf{R}_E . \, \mathbf{I_E}^2$$

- Armature Joule losses:

$$P_{IA} = R_A \cdot I_A^2$$



- Useful electrical power / electromagnetic power:

$$P_{EM} = E. I_A = U_A. I_A - P_{JA}$$

- Constant losses: iron losses + mechanical losses:


$$\mathbf{P_C} = \mathbf{P_f} + \mathbf{P_m} = \mathbf{P_0} - \mathbf{R_A} \cdot \mathbf{I_A}^2 = \mathbf{C_P} \cdot \mathbf{\Omega}$$

=> Can be represented by a loss torque (Cp)





- Characteristic equations:



- Useful power: 
$$P_U = U_A$$
.  $I_A - P_{JA} - P_C = C_U$ .  $\Omega$ 

- Efficiency: 
$$\eta = \frac{P_U}{P_{AbsTot}}$$





- Expressions of torques:

- Electromagnetic torque:

$$C_{EM} = \frac{E.I_A}{\Omega} = \frac{E.I_A}{2.\pi.n}$$

$$C_{EM} = \frac{1}{2.\pi} \cdot \frac{p}{a} \cdot N. \Phi. I_A = k. \Phi. I_A$$

=> If the flux is constant,  $C_{EM}$  is proportional to  $I_A$  ( $k_C$ : torque constant, in N.m.A<sup>-1</sup> (manufacturer's data))

- Loss torque: 
$$C_P = \frac{P_0 - R_A \cdot I_{A0}^2}{2 \cdot \pi \cdot n}$$

=> Due to iron losses in the rotor (hysteresis + eddy currents) and to mechanical losses (bearing friction, brush friction on the collector). It can be estimated from a no-load test

- Useful torque: 
$$C_U = C_{EM} - C_P = \frac{P_U}{2.\pi.n}$$
 => Also called driving torque






## The DC motor:summary

- Mechanical equations:
- Fundamental principle of dynamics applied to a rotating solid:  $J \frac{d\Omega}{dt} = C_M C_R$ 
  - => C<sub>M</sub> is the driving torque, C<sub>R</sub> the resistant torque and J the moment of inertia
- With the electromagnetic torque:  $C_{EM} = k. \Phi. I_A$
- <u>Electrical equations:</u>
- Counter electromotive force:  $E = k \cdot \Phi \cdot \Omega$
- Voltage at the terminals of the armature:  $m{U}-m{E}=m{R}.\,m{i_A}+m{L}.rac{dm{i_A}}{dm{t}}$   $U=E+R.\,I_A$



#### - Speed variation:

- Industrial variable speed drive consist of an all-thyristor, single-phase or three-phase, head-to-tail double bridge supplying the armature, enabling operation in all four quadrants, and a mixed bridge for the inductor.
- => Speed varied by playing on the armature voltage



- Small permanent-magnet motor use a switch-mode power supply.

